

Characteristics



- Apt for air and non aggressive gas
- All models are available with two measurement ranges of pressure that can be selected by the user through internal switch. At the characteristics table there can be only seen the main work scale
- Viewing of the measured value by means of red LEDS display, of 3,5 digits
- Options: Output signal 4...20 mA, versions without LED screen, additional witching output, etc.
- Some models require minimum quantity

Specifications

Model	Escala de trabajo (Pa)	Presión máxima (mbar)	Señal de Salida (∀)	Conexiones
984M.523714	0 - 100	200	0,,,10V	PA 2xØ6mm
984M.533714	0 - 250	200	0,,,10V	PA 2xØ6mm
984M.543714	0 - 500	200	0,,,10V	PA 2xØ6mm
984M.553714	0 - 1000	400	0,,,10V	PA 2xØ6mm
984M.573714	0 - 5000	600	0,,,10V	PA 2xØ6mm
984M.593714	0 - 25000	3000	0,,,10V	PA 2xØ6mm
984M.5B3714	0 - 100000	12000	0,,,10V	PA 2xØ6mm